

Shihlin PG301L/PG301C CPU firmware (V0.110→V0.120) update description

Thank you for choosing and supporting Shihlin electric products.

The following is description of Shihlin PG card PG301L/PG301C CPU firmware update (V0.110→V0.120)

A、Objective models：

SNKPG301L、SNKPG301C

B、Version update check：

method	before update	after update
In INV P.124	0.110	0.120
PG card package label	 <p>Shihlin PG CARD Style No. : PG301L Applied to: SHIH LIN FA PRODUCTS Serial No.: PGAHNAS18K0001 MFG. No. : DU1811017 Suzhou Shihlin Electric & Engineering Co.,Ltd MADE IN CHINA</p>	 <p>Shihlin PG CARD Style No. : PG301L Applied to: SHIH LIN FA PRODUCTS Serial No.: PGAHNAS18K0001 MFG. No. : DU1811017 Suzhou Shihlin Electric & Engineering Co.,Ltd MADE IN CHINA</p>

C、Purpose of modification：

No.	description
1	Reduce the pulse count error between AOBO(upper controller) and A1B1(PG card) during zero servo

D、Effective date

1. Start from Feb.2019

general confidential secret top secret

Release Date	2019-2-14	Parts Name	Shihlin PG301L/PG301C CPU firmware (V0.110→V0.120) update description	Shihlin Electric Automation Group
--------------	-----------	------------	---	-----------------------------------